

## **COMPLAINT INSPECTION REPORT**

Project Name:	Mountain Valley Pipeline	Inspector:	John McCutcheon
Inspection Date:	Wednesday, August 15, 2018	Project Contact:	Brian Clauto, Tracy Hilbun
Spread:	Spread I	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)					
☐ Clearing ☐ Rough Grading ☐ Trench Exc	avation	Pipe Assembly, Testing & Installation			
☐ Backfilling and Grade Restoration ☐ Final Grading & Stabilizar	tion	Other: Archeological excavation			
	Yes No N/A				
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?					
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?					
3 Areas of offsite sediment deposition were observed?					
Comments: This report is for an inspection at an area Franklin County at the archeological excavation site near Stream Crossing S-II2 and STA 13916+51, in response to a complaint that excavations are continuing while a stop work order is in effect and that water is being pumped from pits into a stream unfiltered.  1. The FERC-issued stop work order did not include this cultural resource investigation work.  2. The excavation site is well-managed with E&S controls and sediment is not leaving the work area.  3. Water pumped from the excavation is being discharged through a filter-bag. Pump and fuel protected by pollution prevention measures.					
Deadline: N/A  The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.  Inspector Signature:					



## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Wednesday, August 15, 2018



Excavation site well-protected with E&S controls and vegetated buffer.



Trench dewatering hose leading to filter bag and silt fence.

## Comment 2



Pollution prevention measures for pump and fuel.